

HP Firmware Release Sets for Workstations

Downloads & Compatibility



NOTE: The table below lists the current release sets and their valid point releases. A release set can be customized to contain any valid interim point releases as shown in the release set compatibility table below. These point releases can be customized to the current release set or the two back and are valid.

Note: Windows and Linux are shown side by side, not sequentially as in previous tables.

Smart Update Firmware DVD version (contains)	9.00	9.10C	9.20b			
HP BladeSystem c-Class Firmware Components	Release Set 2010.03	Release Set 2010.07	Release Set 2010.10			
	Windows	Linux	Windows	Linux	Windows	Linux
Onboard Administrator Firmware Component	2.60 , 3.00 , 3.11 , 3.21	2.60 , 3.00 , 3.11 3.21	3.10 , 3.11 , 3.21	3.10 , 3.11 , 3.21	3.11 , 3.21	3.11 , 3.21
HP Integrated Lights-Out 2	1.81 , 1.82 , 2.01	1.81 , 1.82 , 2.01	1.82 , 2.01	1.82 , 2.01	2.01	2.01

Virtual Connect Firmware, Ethernet plus 4/8Gb 20-port FC Edition	<u>2.32</u>	<u>2.32</u>				
HP BladeSystem c-Class Virtual Connect Firmware, Ethernet plus 4/8Gb 20-port and 8Gb 24-port FC Edition	<u>3.0, 3.10, 3.15</u>	<u>3.10, 3.15</u>	<u>3.01, 3.10, 3.15</u>	<u>3.10, 3.15</u>	<u>3.10, 3.15</u>	<u>3.10, 3.15</u>
Smart Array P212, P410, P410i, P411, P712m and P812	<u>3.00, 3.50, 3.52</u>	<u>3.00, 3.50, 3.52</u>	<u>3.00, 3.50, 3.52</u>	<u>3.00, 3.50, 3.52</u>	<u>3.52</u>	<u>3.52</u>
HP Firmware Flash for QLogic Fibre Channel Host Bus Adapters		<u>2010.03.17, 2010.05.19</u>		<u>2010.05.19</u>		<u>2010.05.19</u>
HP Firmware Flash for Emulex Fibre Channel Host Bus Adapters		<u>2010.01.20, 2010.04.05(a)</u>		<u>2010.04.05(a)</u>		<u>2010.04.05(a)</u>
WS460c G6	<u>2010.01.14, 2010.03.01, 2010.03.30, 2010.08.16, 2010.09.02</u>	<u>2010.01.14, 2010.03.01, 2010.03.30, 2010.08.16, 2010.09.02</u>	<u>2010.03.30, 2010.08.16, 2010.09.02</u>	<u>2010.03.30, 2010.08.16, 2010.09.02</u>	<u>2010.08.16, 2010.09.02</u>	<u>2010.08.16, 2010.09.02</u>

	,	<u>2010.08.16</u>				
	,	<u>2010.09.02</u>				

Note:

- Firmware must not be updated using the FW DVD in online mode, but in offline mode only.
- While upgrading using the FW DVD ISO image through IRC, the ISO image will be unmounted during the iLo firmware upgrade. If this happens, run the upgrade again for only the failed components.
- The NVIDIA firmware is not included in the FW DVD set. Hence it has to be upgraded separately.